

General Environmental Incident Summary

Incident: 3584 **Date/Time Notice:** 12/18/2014 1047 **DEM Incident No:**
Responsible Party: Bridger Transfer
Date Incident: 12/17/2014 **Time Incident:** 1430 **Duration:** 1 minutes
County: Mountrail **Twp:** 156 **Rng:** 91 **Sec:** 27 **Qtr:**
Lat: 48.30328 **Long:** -102.37360 **Method:** Interpolation from map
Location Description: Bridger Transfer Services, LLC, Stanley 3B Facility, 6150 Hwy 8, Stanley, ND 58784

Submitted By: Otis Randle **Affiliation:** Director of Environmental Safety
Address: 800 Spring Street; Suite 205
City: Shreveport **State:** LA **Zip:** 71101

Received By:

Contact Person: Otis Randle
2009 Chenault Drive
Carrollton, TX 75006

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 10.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Equipment was recently replaced. Contractor failed to secure all of the bolts on the flange causing the release.

Risk Evaluation:

No immediate risks

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

No potential impact. Contaminated soil was removed for disposal.

Action Taken or Planned:

Transfer of crude oil was stopped and contained by absorbent material. A clean-up contractor was called to remediate the impacted soil for removal and disposal. Equipment contractor was called in to secure all bolt heads.

Wastes Disposal Location: Gibsons, Williston, ND

Agencies Involved:

Updates

Date: 12/18/2014 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Small volume release at a new installation. Report stated that the impacted soil has been removed and the installation mistake corrected. No on-site inspection is needed in this case.